


Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

131

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\131.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 131 Date: $^{9/24/2004}$ MeterBasin: 01 _WRR02 Observer ID: B Crew: $^{T-1}$ Dve Test Recommended: N

Defect No: 2 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

2201 Rogene DR

Source Type: 01= Main Sewer **Location:** 11=Field **Severity:** 4=Major

Sector: 1=Public Drainage Area: 50000

Comments: hole in stream bed

SMOKE TEST PHOTOS



Photo No: 21

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0924-2004\T-1\PLAYER_B\B_2004_0924Image0021.JPG

Image Status: Image found and displayed.



Photo No: 22

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0924-2004\T-1\PLAYER_B\B_2004_0924Image0022.JPG

Image Status: Image found and displayed.



Photo No: 23

Filename Path:


 $X.\\Baltimore\ City\\Western\ Run\ Pilot\ Area-Data\ Files\\Smoke\ Testing\\Pictures\\0924-2004\\T-1\\PLAYER_B\\B_2004_0924\\Image0023.JPG$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

131

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\131.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 131 Date: 9/24/2004 MeterBasin: 01_WRR02
Observer ID: B Crew: T-1 Dve Test Recommended: N

Defect No: 3 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

2201 Rogene DR

Source Type: 12= MH Frame Seal **Location:** 11=Field **Severity:** 4=Major

Sector: 1=Public Drainage Area: 50000

Comments: M.H # 0692132

SMOKE TEST PHOTOS



Photo No: 25

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0924-2004\T-1\PLAYER_B\B_2004_0924Image0025.JPG

Image Status: Image found and displayed.

Photo No: 24

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\0924\-2004\T-1\PLAYER_B\B_2004_0924\Image0024\JPG$

Image Status: Image found and displayed.

Photo No:


Filename Path:





Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

131

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\131.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

House Number	Street P	refix: Stre	et Name:	Street Type:	
Defect No:	0	Setup No:	: 4	Priority CCTV:	
Observer ID:		Crew:	T-1	Dve Test Recommended:	N
Unique Test ID	132	Date:	9/24/20	MeterBasin:	

Source Type: Location: **Severity:**

Sector: Drainage Area:

Comments: No defects observed

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

132

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\132.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 132 Date: 9/24/2004 MeterBasin:

Observer ID: B Crew: T-1 Dye Test Recommended: N

Defect No: 1 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

6060 Green Meadow PKWY

Source Type: 12= MH Frame Seal **Location:** 14=Other **Severity:**

Sector: 2=Private Drainage Area: 200

Comments:

SMOKE TEST PHOTOS



Photo No: 2

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0924-2004\T-1\PLAYER_B\B_2004_0924Image0027.JPG

Image Status: Image found and displayed.

Photo No: 26

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\0924\-2004\T-1\PLAYER_B\B_2004_0924\Image0026\JPG$

Image Status: Image found and displayed.

Photo No:


Filename Path:





Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

132

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\132.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 133 Date: $^{9/27/2004}$ MeterBasin: $^{01}_WR03$ Observer ID: B Crew: $^{T-1}$ Dye Test Recommended: N

Defect No: 1 Setup No: 1 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

5920 Green Meadow PKWY

Source Type: 02= Service Line **Location:** 5=Sidewalk **Severity:**

Sector: 2=Private Drainage Area: 180

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_B\B_2004_0927Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_B\B_2004_0927Image0001.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

133

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\133.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 133 Date: 9/27/2004 MeterBasin:

Observer ID: B Crew: T-1 Dye Test Recommended: N

Defect No: 2 **Setup No:** 1 **Priority CCTV:**

House Number Street Prefix: Street Name: Street Type:

5924 Green Meadow PKWY

Source Type: 02= Service Line **Location:** 7=Yard-Front **Severity:**

Sector: 2=Private Drainage Area: 100

Comments:

SMOKE TEST PHOTOS



Photo No: 4

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_B\B_2004_0927Image0004.JPG

Image Status: Image found and displayed.

Photo No: 3

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_B\B_2004_0927Image0003.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

133

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\133.tif

Image Status: Image found and displayed.





Western Run Pilot Project - Baltimore Maryland

Unique Test ID 134 Date: 9/27/2004 MeterBasin:

Observer ID: A Crew: T-1 Dye Test Recommended: N

Defect No: 1 **Setup No:** 2 **Priority CCTV:**

House Number Street Prefix: Street Name: Street Type:

Green Meadow PKWY

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:**

Sector: 1=Public **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0001.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

134

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\134.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 134 Date: 9/27/2004 MeterBasin:

Observer ID: A Crew: T-1 Dye Test Recommended: N

Defect No: 2 **Setup No:** 2 **Priority CCTV:**

House Number Street Prefix: Street Name: Street Type:

Green Meadow PKWY

Source Type: 02= Service Line **Location:** 7=Yard-Front **Severity:**

Sector: 1=Public Drainage Area: 25

Comments:

SMOKE TEST PHOTOS



Photo No: 4

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0004.JPG

Image Status: Image found and displayed.

Photo No: 3

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0003.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

134

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\134.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 134 Date: 9/27/2004 MeterBasin:

Observer ID: A Crew: T-1 Dye Test Recommended: N

Defect No: 3 **Setup No:** 2 **Priority CCTV:**

House Number Street Prefix: Street Name: Street Type:

Green Meadow PKWY

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:**

Sector: 1=Public **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0006.JPG

Image Status: Image found and displayed.

Photo No: 5

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0005.JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

134

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\134.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 134 Date: 9/27/2004 MeterBasin:

Observer ID: A Crew: T-1 Dye Test Recommended: N

Defect No: 4 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

Green Meadow PKWY

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:**

Sector: 1=Public Drainage Area: 0

Comments:

SMOKE TEST PHOTOS



Photo No: 8

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0008.JPG

Image Status: Image found and displayed.

Photo No: 7

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0007.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Page 1676 of 4012

Sketch No:

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\134.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID	134	Date:	9/27/2004	MeterBasin:
-----------------------	-----	-------	-----------	-------------

Observer ID: A Crew: T-1 Dye Test Recommended: N

Defect No: 5 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

Green Meadow PKWY

Source Type: 18= Other **Location:** 6=Curb **Severity:**

Sector: 2=Private Drainage Area: 75

Comments: roof drinage into the street - still smoked

SMOKE	TEST	PHOT	OS

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke$ $Testing\Pictures\V0927-2004\V-1\PLA\YER_A\A_2004_0927Image0010.JPG$

Image Status: Image found and displayed.

Photo No: 9

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0927-2004\T-1\PLAYER_A\A_2004_0927Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: Can't find image in the specified nam



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

134 **Sketch No:**

Filename Path:

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\Sketches\134.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID Observer ID: Defect No:	134 A 6	Date: Crew: Setup No:	9/27/200 T-1 2	D	leterBasin: ve Test Recommended: rioritv CCTV:	N
House Number 6136	Street Pro		Name: Meadow	Street Ty		
Source Type: Sector:	12= MH Fran 2=Private	Loc	ation: inage Area:	6=Curb	Severity:	
Comments: addr	ess is an approx	ζ.				
		SMO	OKE TES	Т РНО	гоѕ	
				Filer	no No: 12 name Path: more City\Western Run Pilot Area - Data Files\	Emaka
				Testing	Pictures\0927-2004\T-1\PLAYER_A\A_2004_0 ge Status: Image found and dis	927Image0012.JPG
					,	
Photo No:	11					
Filename Path:						
X:\Baltimore City\Western Ru esting\Pictures\0927-2004\T-	-1\PLAYER_A\A_2	004_0927Image0011.JP	P G			
mage Status: I	mage found and	d displayed.				
				Phot	o No:	
				Filer	name Path:	
				Imag	ge Status: No image name spec	rified.



Western Run Pilot Project - Baltimore Maryland

FIELD	SKETCH

134 **Sketch No:**

Filename Path:

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\Sketches\134.tif$

Image Status: Image found and displayed.